


# OCA (Optically Clear Adhesive) Data Sheet

**Overview:**

Optically Clear Adhesive(OCA) is used for lamination of glass to glass or bonding glass to another substrate for displays. The adhesive is clear and does not discolor due to heat or light.

**Product Description:**

OCA consists of 2 layers: a release liner and an optically clear adhesive bonded to the glass substrate.



**Specifications:**

Cat-i Glass offers 1 option for OCA in a 2 mil thickness. Glass

Characteristic	Cat-i OCA
Thickness	2 mil
Haze %	.3
Transmittance %	92
Temperature Thresholds	185° F